


CORRECTION TIMING
 XX:57:54-XX:58:02
 5:57:54-5:58:08







Note: The suggestion provided may or may not be suitable for your intended application. Please consider this information carefully before incorporating it into your system design. Valcom disclaims any responsibility for accuracy or completeness.

VALCOM 5614 Hollins Road
 Roanoke, VA 24019
 540-563-2000

**WIRELESS CLOCK HEAD END
 WITH NORMALLY OPEN CONTACTS
 SYNCH CORRECTION SCENARIO**

Drawing # 142
 Revision B



Note: The suggestion provided may or may not be suitable for your intended application. Please consider this information carefully before incorporating it into your system design. Valcom disclaims any responsibility for accuracy or completeness.

VALCOM 5614 Hollins Road
Roanoke, VA 24019
540-563-2000

Drawing # 142
Revision B

**WIRELESS CLOCK HEAD END
WITH NORMALLY OPEN CONTACTS
SYNCH CORRECTION SCENARIO**